



## **HODYON LP – DYNASYS APU EXTENDED APU WARRANTY**

Hodyon LP offers the following Extended Warranty on a new Dynasys APU for the major APU components listed below.

### **Major APU Components Covered**

- Alternator
- Starter
- Fuel Pump
- Water Pump
- Compressor
- Evaporator
- Heating Coils
- Condenser
- Generator
- CCU
- ECM
- Radiator Fan
- Condenser Fan
- Lower APU Cabinet Fan
- The following specific engine parts only: cylinder block, crankshaft forging, connecting rods, flywheel, flywheel housing, camshaft, timing gear, and gear case.

### **Extended Warranty Period**

The Extended Warranty Period is limited to an 36, 48, or 60 months or 6,000, 8,000, or 10,000 hours, respectively, depending on the program, whichever occurs first after date of the APU installation for the first user. This warranty must be purchased at the time of the initial APU purchase, runs concurrently with the standard warranty period, and is limited to the major APU components listed above.

### **Warranty Limitations**

The Hodyon LP Dynasys APU Limited Warranty is incorporated, in full, by reference. Additionally the following apply to this extended warranty:

#### **Use of the Product**

Hodyon LP will have no liability for any Component if Hodyon LP determines that:

- The Product embodying such Component was used for any purpose other than its original stated purpose.
- The Component failure was caused by improper or untimely maintenance of the Hodyon® APU.
- The asserted defect:
  - Is not present,
  - Cannot reasonably be fixed because of damage or malfunction attributable to misuse, inappropriate use, or improper maintenance; or
  - Is attributable to improper installation, alteration, or accident.
- The Product was not sold to you as new.

#### **Additional Limitations on Warranty**

The Hodyon LP Warranty does not cover Products or Components which have been neglected, modified, altered, or physically damaged. All Products and Components will be inspected by Hodyon LP or a Hodyon LP authorized Service and Repair center. Without limiting its ability to consider other relevant factors, the items listed below shall be considered as evidence of neglect, alteration or damage, as applicable, by Hodyon LP:

- Evidence of Neglect
  - Coolant system has signs of not being properly maintained
  - Lubrication system and components show signs of not being properly maintained
  - Air filtration system shows signs of not being properly maintained
  - Records cannot be produced that verify that all required maintenance was performed per Hodyon LP Schedule of Standard Maintenance
  - Engine shows any signs of overheat and/or the heat tab is deformed or missing
- Evidence of Alterations
  - Customer added or modified components
  - Components placed on the Product other than Hodyon LP authorized parts.

- Tampering with any labels, including but not limited to all serial number labels
- Modified wiring
- Missing bottom panel
- Re-routing of hoses or wiring harnesses
- Any evidence of tampering with the CCU or ECM and any and all related components, wiring, and harnessing
- Evidence of Damage
  - Dented cover
  - Dented, cracked, or misaligned frame or any and all mounting brackets
  - Loose, damaged, cracked, or missing bolts, nuts, washers, or connectors
  - Stripped threads on bolts, screws, or mounting holes.
  - Any other evidence that the product or component has incurred damage.

### **Price of Extended Warranty**

The per unit price for the extended warranty is as follows:

<b>Warranty Program</b>	<b>DYNASYS APU</b>	
	<b>Deductible <sup>1</sup></b>	<b>Price</b>
Extended Warranty – 36 months or 6,000 hours	\$250	See Dynasys Dealer
Extended Warranty – 48 months or 8,000 hours	\$250	See Dynasys Dealer
Extend Warranty – 60 months or 10,000 hours	\$250	See Dynasys Dealer

---

<sup>1</sup> The deductible is per warranty event. There is no minimum or maximum for any time period.